To: Lyndsey Nguyen (Nguyen.Lyndsey@epa.gov)[Nguyen.Lyndsey@epa.gov]

From: Daly, Eric

Sent: Fri 8/21/2015 8:19:18 PM

Subject: FW: Pollution Report # (Initial) 1 Niagara Falls Boulevard Radiological Site

NiagaraFallsBoulevardRadiological polrep 1.htm

NiagaraFallsBoulevardRadiological polrep 1 IMG 0455.jpg NiagaraFallsBoulevardRadiological polrep 1 IMG 0443.jpg

This was the first PolRep I sent out for Niagara Falls Boulevard Site.

From: Daly, Eric

Sent: Tuesday, July 28, 2015 5:03 PM

To: Mugdan, Walter; Carpenter, Angela; Enck, Judith

Cc: Daly, Eric; Bellis, Mark; Mosher, Eric; Daloia, James; Wilson, Eric; Hriczko, Bonnie; Giardina, Paul; Povetko, Oleg; Koehler, Larainne; Smith, Lora; Fessler, Andrew; Hauptman,

Mel; Kluesner, Dave; Basile, Michael; 'Paul.Dicky@niagaracounty.com';

'lwallace@townofniagara.com'; 'cynthia.costello@health.ny.gov';


'stephen.gavitt@health.ny.gov'; 'jerry.collins@health.ny.gov'; 'timothy.rice@dec.ny.gov'; 'thomas.papura@dec.ny.gov'; 'gregory.sutton@dec.ny.gov'; 'kenneth.martin@dec.ny.gov'; 'jerry.riggi@dec.ny.gov'; Oldland, Colin; Freeman, Martin; Grealish, Beckett; Zachos, George; Doyle, James; Pane, Mark; Grealish, Beckett; Harkay, Dan; Kodama, Doug; Banner, Ellen; Gaughan, Daniel; Perera, Dilshad

Subject: Pollution Report # (Initial) 1 Niagara Falls Boulevard Radiological Site

Good Afternoon:

USEPA Pre-Remedial Program performed an assessment at the Niagara Falls Boulevard Site (NFB) in 2013-2014. Based on the Pre-Remedial Evaluation, a recommendation of **NO FURTHER REMEDIAL ACTION PLANNED (NFRAP)** was given for the Niagara Falls Boulevard site. However, it was determined that further assessment should be performed and the site was referred to the USEPA Removal Program.

On June 16, 2015, OSC Daly was assigned as the lead on-scene coordinator for Niagara Falls Boulevard Radiological Site.



Preliminary draft results indicate that there are no elevated gamma or radon/thoron readings within the occupied spaces of one building at the site. However, the second building exhibited some "hot spots" or defined areas that had elevated gamma readings. These areas appear to be portions of the building that were additions to the original building. Meaning, the construction of the additions occurred after the contaminated fill was in place and therefore, the radioactive material is located below the concrete slab of these sections.

Public Affairs

o Legal Staff

OSCs and Weston tentatively plan to return to NFB Site the week of August 10, 2015 to perform radon canister sampling in both buildings as

well as Geo Probe Soil Boring Sampling at specific points along the property that was not assessed by the Pre-Remedial Program.

Attached is a Pollution Report (POLREP) regarding:

USEPA Region II

Niagara Falls Boulevard Radiological Site

9524-9540 Niagara Falls Boulevard, Niagara Falls, NY

To view this POLREP, please open the attachment.

Lotus Notes Users, please Launch the attachment.

For additional information regarding this site, please visit the website by clicking on this link:

http://www.epaosc.org/NiagaraFallsBoulevardRadiological

Regards,

Eric

"We must, indeed, all hang together, or assuredly we shall all hang separately ", Benjamin Franklin Eric M. Daly On-Scene Coordinator/Radiological Response Specialist US Environmental Protection Agency- Region II

ERRD/RPB/PPS
2890 Woodbridge Avenue
Edison, NJ 08837
daly.eric@epa.gov
732-321-4350